UTAH STATE CAPITOL ARCHITECTURE: INTERIOR PRESERVATION I SURVEY REPORT

100ve East Vestibule 1st Floor

Dimension/S F

Original Use

East Vestibule 1st Floor

Preservation Level I



Element Code B-1

Element Code Gray marble base, 12" polished

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity

Notes



Element Code CL-04

Element Code Plaster ceiling, smooth, flat,

painted

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity

Notes



Element Code CPP-19

Element Code Gray Georgia marble post, solid

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity 2

Notes



Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

Condition Fair

Repair/Replace No

Quantity

Notes Mouldings are in fair condition -

a few dirt/burn spots? Should be

checked.



Element Code D-10

Element Code Metal wood-grained panel door

with matching casing. Bankers glass panel and transom

Historical Significance Significant

Condition Good

Repair/Replace

Quantity 3pr

Notes



Element Code D-33

Element Code Aluminum exterior doors with

glass panels and transoms

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity 3pr

Notes



Element Code E-6

Element Code Paging intercom w/ switch

Historical Significance Non Contributory

Condition

Repair/Replace

Quantity

Notes



Element Code F-1

Element Code Gray Georgia marble floor,

polished square

Historical Significance Very Significant

Condition

Repair/Replace

Quantity

Notes



Element Code F-2

Element Code Tile floor, hex & square, mosaic

Historical Significance Significant

Condition Poor

Repair/Replace

Quantity

Basic Pattern, 1" hex on field.



Element Code HC-10

Element Code vent

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity

Notes



Page XIX.IX.88



Element Code L-17

Element Code Ceiling lamp mounted, cylindrical

Historical Significance Contributory

Condition Fair

Repair/Replace No

Quantity 3

Notes



Element Code W-19

Element Code white onyx travertine wall

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity

Notes



Page XIX.IX.89

200

Governor's Board Room

Dimension/S F 32'-7" x 24'-10"

Original Use

Governor's Board Room

Preservation Level I



Element Code B-10

Element Code Wood base block

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity 1

Notes south door



Element Code Plaster ceiling with stenciling

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code Ornamental band: stenciled

panel beneath cornice

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes perimeter







Element Code B-6

Element Code Plaster base, painted

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes faux bois 6" grained, not

original? Very simple

Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes egg & dart, gold eggs

Element Code F-11

Element Code Carpeted floor, on pad

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity









Element Code HC-10

Element Code vent



Historical Significance Non-Contributory Condition Good

Repair/Replace No

Quantity 3

Notes



Element Code HC-13

Element Code Heater/Air Conditioner, fan coil

Historical Significance Non-Contributory

> Condition Good

Repair/Replace

Quantity

Notes



Element Code L-11

Element Code Ceiling lamp suspended,

incandescent, 1/2 round globe,

historic

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity 4

Notes



Element Code L-12

Element Code Indirect cove lighting

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes



Element Code L-15

Element Code Track lighting

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity

Notes



Element Code M-6

Element Code Metal wood-grained casing w/

fancy profile

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

on D-6 to reception area, also Notes

with H-2



Element Code SP-10

Element Code Furniture now NHF

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes table 8' x 15', rounded edge (4

tables together)

chairs: 23 high-back; 29 low-

back

Element Code SP-18

Element Code drapery

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity

Notes not original

Element Code WN-9

Element Code Leaded glass window, interior

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 1

Notes Back view has diffused cover.







Element Code SP-12

Element Code Walled or screened storage

Historical Significance Non Contributory

Condition Good

Repair/Replace

Quantity 1

Notes Roller screen.



Element Code W-7

Element Code Plaster wall, painted and smooth

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity



200vs

South Vestibule 2nd Floor

Dimension/S F

Original Use

South Vestibule 2nd Floor

Preservation Level I



Element Code B-1

Element Code Gray marble base, 12" polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code BA-18

Element Code Ornamental plaster beam

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code CL-04

Element Code Plaster ceiling, smooth, flat,

painted

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code CPP-17

Element Code creamy white onyx travertine

pilaster

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code CPP-18

Element Code creamy white onyx travertine

posts

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code D-10

Element Code Metal wood-grained panel door

with matching casing. Bankers glass panel and transom

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity 3pr

lotes Doors have metal kick plates



Element Code D-31

Element Code Ornamental bronze doors,

exterior

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity 3pr

Notes Main door

Element Code HC-10

Element Code vent

Historical Significance Non Contributory

Condition Good

Repair/Replace

Quantity

Notes

Element Code SP-21

Element Code Plaque - marble carving

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity 2

Notes







Element Code F-23

Element Code white onyx travertine floor/ front

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes Onyx travertine main flooring.

Grey marble in polished squares

as accent pattern.

Element Code L-17

Element Code Ceiling lamp mounted, cylindrical

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity

Quantity (2) longer light fixture, Notes

Quantity (4) shorter light fixture

Element Code W-19

Element Code white onyx travertine wall

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity





201

Vestibule to Lieutenant Governor's Area

Dimension/S F 12'-8 1/2" x 11'-11

Original Use

Main Corridor 2nd floor

Preservation Level I



Notes similar to 208K includes 209 - vestibule to offices - south of lobby.

Element Code B-14

Element Code white marble base

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes north and west walls



Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

Good Condition

Repair/Replace No

Quantity

Notes



Element Code D-06

Element Code Metal wood grained panel door with frosted glass panels.

Casing is decorative wood or

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 1

Notes



Element Code CL-04

Element Code Plaster ceiling, smooth, flat,

painted

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code CR-7

Element Code Ornamental band: stenciled

panel beneath cornice

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity 2

Notes



Element Code F-1

Element Code Gray Georgia marble floor,

polished square

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

Notes south and west walls



Element Code F-15

Element Code Floor rug/carpet

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity

Notes antique circular Bijar(?)

matching rug in 203G



Element Code L-11

Element Code Ceiling lamp suspended,

incandescent, 1/2 round globe,

historic

Historical Significance Very Significant

Good Condition

Repair/Replace No

Quantity 1

Notes



Element Code M-19

Element Code Wood casing, new

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes on door to lobby



Element Code HC-15

Element Code Duct in fake beam, new, with

ornamental grille

Historical Significance Non-Contributory

> Condition Good

Repair/Replace

Quantity 2

> Notes north and east walls



Element Code M-17

Element Code Marble picture rail

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

with gold bead Notes



Element Code M-6

> Element Code Metal wood-grained casing w/

fancy profile

Historical Significance Significant

> Condition Good

Repair/Replace No

Quantity

Metal wood-grained casing with

fancy profile specific to Room 201. Wood specific to Room

209.



Element Code MS-6

Element Code Plaque, Metal with room #,

name, wall-mounted

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 2

Notes Specific to Room 201.



Element Code MS-8

Element Code Metal key panel, Newman Clock

Co.

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity 1

Notes



Element Code SP-13

Element Code Storage cabinet, free-standing

with marble base B-1

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity '

Notes in east wall, with B-1



Element Code MS-7

Element Code Bell, old or original

Historical Significance Significant

Condition Good

Repair/Replace N

Quantity

Notes painted gold. Specific to Room

201.

Element Code SP-10

Element Code Furniture now NHF

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 5

Notes reproduction chairs

Element Code W-1

Element Code Gray marble wall, polished

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes north and west walls







Element Code W-20

Element Code Glass panel wall

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 2

Notes north and east walls



205

Governor's Formal Office

Dimension/S F 18'-8 1/2" x 24'-2"

Original Use

Governor's Formal Office

Preservation Level I



Element Code B-9

Element Code Marble base, antigua verde

(Vermont)

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity

Notes 6" original?



Element Code CL-10

Element Code Plaster ceiling, molded and

decorative

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes With cream, brown and beige

stenciling



Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

Good Condition

Element Code Floor rug/carpet

Good

Repair/Replace No

Quantity

Element Code F-15

Historical Significance Contributory

Condition

Repair/Replace No

Quantity

Egg and dart both gold painted, Notes

dentils light brown



Element Code D-11

> Element Code Metal wood-grained panel door

with matching casing. Plain

louver transom

Historical Significance Contributory

> Condition Good

Repair/Replace No

Quantity 1

to stair with reproduction Notes

hardware and metal panel, wood

casing panel

Element Code F-3

Element Code Original wood floor: maple

Historical Significance Very Significant


> Condition Good

Repair/Replace No

Quantity

dark mahogany finish Notes







reproduction of original rug?

Element Code HC-10

Element Code vent



Element Code HC-16

Element Code wood-panelled duct/vent in

window sill

Historical Significance Non-Contributory

> Condition Good

Repair/Replace

Quantity 2

Notes



Historical Significance Non-Contributory

Condition Good

Repair/Replace

Quantity 4

Notes

Element Code L-13

Element Code Chandelier, historic 18 globe,

board room

Historical Significance Very Significant

Good Condition

Repair/Replace No

Quantity

Notes



Element Code L-16

Element Code TV lights, hidden behind

movable panel SP-19

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity 4

Notes



Element Code M-8

Element Code Plaster ceiling medallion for

chandelier

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code SP-18

Element Code drapery

Historical Significance Contributory

> Condition Good

Repair/Replace No

Quantity

Old balloon valance with new Notes

hardware



Element Code SP-19

Element Code Movable panels, hiding TV lights

L-16

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity

Notes



Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure on originallity (2) 18"X27"

Reupholstered Sofa, hand

carved feet



Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

Condition Good

Repair/Replace N

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure

on originallity (2) 18"X27" Reupholstered Sofa, hand

carved feet

Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure on originallity (2) 18"X27"

Reupholstered Sofa, hand

carved feet





Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure on originallity (2) 18"X27" Reupholstered Sofa, hand

carved feet

Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure on originallity (2) 18"X27"

Reupholstered Sofa, hand

carved feet





Element Code SP-9

Element Code Furniture now HF

Historical Significance Significant

> Condition Good

Repair/Replace

Quantity

Notes Oval Desk, 2 sided 6'9" X 41"

Federal oval table 6'X45" - (leaf

missing frm center)

Federal side table with brass

feet 6'3"X2'

Federal Chest 3'4"X1'10" End tables - wood inlay, unsure on originallity (2) 18"X27"

Reupholstered Sofa, hand

carved feet

Element Code W-7

Element Code Plaster wall, painted and smooth

Historical Significance Contributory


Condition Good

Repair/Replace No

Quantity

Wall thicker than depth of cornice





Element Code WS-3

Element Code Wood wainscot

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes Hand grained??



210

Governor's Main Reception

Dimension/S F 12'-8 1/2" x 39'-8

Original Use

Main Corridor 2nd

Preservation Level I





Notes when the glass wall was added in 1993, a private foyer was created, purportedly saving the Board Room from becoming a passage and even the Gold Room from becoming the new board room.

Element Code B-1

Element Code Gray marble base, 12" polished


Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes new on east glass wall



Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

Good Condition

Repair/Replace No

Quantity

with gold bead Notes



Element Code D-11

Element Code Metal wood-grained panel door

with matching casing. Plain

louver transom

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 2

Notes with etched glass

to vestibules with H-2



Element Code CL-04

Element Code Plaster ceiling, smooth, flat,

painted

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code CR-7

Element Code Ornamental band: stenciled

panel beneath cornice

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity 3

Notes



Element Code D-11

Metal wood-grained panel door Element Code

with matching casing. Plain

louver transom

Historical Significance Contributory

> Condition Good

Repair/Replace No

> 2 Quantity

> > with new wood panel

doors to board room, with SP-16

transom, recorded as board

room element



Element Code F-1

Element Code Gray Georgia marble floor,

polished square

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code F-15

Element Code Floor rug/carpet

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity 3

Notes persian rugs



Element Code HC-15

Element Code Duct in fake beam, new, with

ornamental grille

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity 3

on south, east, north sides Notes

obscuring capitals



Element Code L-11

Element Code Ceiling lamp suspended,

incandescent, 1/2 round globe,

historic

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity 1

Notes



Element Code M-17

Element Code Marble picture rail

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code SP-10

Element Code Furniture now NHF

Historical Significance Contributory

> Condition Good

Repair/Replace No

Quantity

reproduction chairs Notes



Element Code SP-10

Element Code Furniture now NHF

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes reproduction chairs



Element Code SP-10

Element Code Furniture now NHF

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes reproduction chairs



Element Code SP-10

Element Code Furniture now NHF

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity

Notes reproduction chairs



Element Code W-19

Element Code white onyx travertine wall

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code W-20

Element Code Glass panel wall

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity

Notes east wall



Element Code WN-7

Element Code Wood transom

Historical Significance Contributory

Condition Good

Repair/Replace No

Quantity 1



Element Code WN-8

Element Code Interior sidelight window, metal



Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity 2

212

Gold Room

Dimension/S F

Original Use Gold Room

Preservation Level I



Element Code B-11

Element Code Golden "onyx" base, 8" in two

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code BA-10

Element Code Corbel bracket, scroll, gilt with

flower ornament

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity 10

> Notes where beams intersect walls



Element Code BA-9

Element Code

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code CL-05

Element Code Coffered plaster ceiling, beams,

ornamental, with molding

Historical Significance Significant

> Condition Good

Repair/Replace

Quantity 11

Notes



Element Code CL-13

Element Code Ceiling painting: oil on canvas

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

"Children at Play" Notes



Element Code CR-11

Element Code wood/plaster valance,

gilt/painted, central shield motif,

foliated cornice

Historical Significance Significant

Condition Good

Repair/Replace

Quantity 4

Notes at windows



Element Code CR-8

Good

Element Code Plaster frieze, foliated lower

band, horiz.panels

Historical Significance

Very Significant

Condition

Repair/Replace

Quantity

Notes



Element Code CR-9

Element Code Plaster crown molding:

egg&dart, dentils, foliated band,

bead band, gilt

Historical Significance

Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code

D-05

Element Code Metal wood-grained panel door

with matching casing

Historical Significance Very Significant

Fair Condition

Repair/Replace

Quantity 2pr

Notes

Pocket door sets, with plaster transom above. Matching other

plaster panneling in room

Element Code E-11

Element Code fire alarm

Historical Significance Non Contributory

Condition Fair

Repair/Replace

Quantity

Notes Placed with in the crown

molding - ceiling decoration





Element Code D-11

Element Code Metal wood-grained panel door

with matching casing. Plain

louver transom

Historical Significance Significant

> Condition Good

Repair/Replace No

Quantity 4

Notes



Element Code E-5

> Element Code Brass floor outlet, round and

flush

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 4



Element Code E-9

Element Code Switch, with non-original plate

Historical Significance Non-Contributory

Condition Good

Repair/Replace

Quantity

Notes



Element Code F-15

Element Code Floor rug/carpet

Historical Significance Contributory

Condition Good

Repair/Replace N

Quantity

Notes Reproduction of original custom

Scotch Chenille rug



Element Code F-20

Element Code Fireplace hearth floor, tile inset

with Golden "onyx" border

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 2

Notes



Element Code F-4

Element Code Original wood floor: quartered

oak "parquet"

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code H-4

Element Code Drapery tie, ornamental brass,

wall-mounted at windows

Historical Significance Very Significant

Condition Fair

Repair/Replace

Quantity

Notes



Element Code H-5

Element Code Drapery tie, simple, at pocket

doors

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Page XIX.IX.116

Element Code H-6

Element Code door hardware: hand pulls

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code door hardware: recessed finger

pulls, original

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes several historic elements: see

furniture survey







Element Code door hardware: dead bolts,

original

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code HC-18

Element Code Ornamental brass heat register,

new, compatible

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity 4

Notes



Element Code L-20

Brass wall sconce, 3-armed Element Code

brass with hanging French teardrop crystals and cut-glass

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity 10



Element Code L-21

Element Code French crystal chandelier, round

suspended brass fixtures with cut-glass ornament and variety

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity 4

Notes



Element Code M-25

Element Code 1" Ornamental plaster wall panel

frame, gilt/painted, foliated

Historical Significance Very Significant

Good Condition

Repair/Replace

Quantity

Notes



Element Code M-29

Element Code Plaster transom panel, double:

gilt/painted with cartouche, cornucopia, floral wreath,

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes 4 - Identical over single doors

2- Identical over the double doors



Element Code M-24

Element Code Golden Onyx chair rail, polished

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code M-26

> Element Code Tapestry cloth panel, w/ crowns,

animals, flowers

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code M-29

> Element Code Plaster transom panel, double:

gilt/painted with cartouche,

cornucopia, floral wreath,

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

4 - Identical over single doors

2- Identical over the double doors



Element Code M-31

Element Code Plaster cupids, gilt/painted with

cartouche, "palm" leaf and laurels

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes on ceiling, north and south of

mural

Element Code M-33

> Element Code Plaster crowning ornament, Eagle over shield above mirror

MS-12

Historical Significance Very Significant

Good Condition

Repair/Replace

Quantity

Notes

Element Code M-35

> Element Code Plaster coffer panel, Central cartouche (attached beehive)

with leaves & berries, gilt

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code M-32

Element Code Golden "Onyx" mantle, w/

classical moulding, fluted scroll

supports at sides

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code Plaster coffer panel, 2

ornamental bands, gilt oak leaves, painted acorns

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes

M-9

Historical Significance

Condition Good

Repair/Replace

Notes





Plaster ceiling ornament, bands Element Code

of running ornament

Very Significant

Quantity



Element Code MS-11

Element Code Andirons (fireplace), cast iron,

with finials

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code W-7

Element Code Plaster wall, painted and smooth

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity

Notes



Element Code MS-12

Element Code Ornate bevelled glass Mirror,

with gilt/painted plaster frame, with ornamental bands, and M-

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code WS-1

Element Code Golden Onyx wainscot, polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity



280

Atruim, Rotunda, main corridors

Dimension/S F

Original Use

Atruim, Rotunda, main corridors

Preservation Level I



Notes Includes the 3rd and 4th floor corridors, 380 and 470 respectively.

UTAH STATE CAPITOL RENOVATION PLANNING SITE ANALYSIS COOPER ROBERTS ARCHITECTS TEAM

Element Code B-1

Element Code Gray marble base, 12" polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes This base is found in the

cooridoor areas on the 1st - 4th floors. The atrium area in the Rotunda has a marble base included in the wainscot. Because of past remodels, this base has been removed and added to new/original walls. No system or order was discovered to where the base was moved to.

Element Code BA-17

Element Code Corbel Bracket capitol

Historical Significance Very Significant

Condition

Repair/Replace

Quantity

Notes West side of the South West

Rotunda pier at a formal hall entrance. No others have been

noticed.



Element Code BA-02

Element Code Cased marble arch, coffered

underside, flower medallions

Historical Significance Very Significant

Condition

Repair/Replace

Quantity

Notes The main archways in the

Rotunda are made of marble the rosettes are terra cotta. This design motif is continued in the archways over the 4th floor doors to the Rotunda piers. The rosettes in this case are plaster.



Element Code CL-02

Element Code Skylight, flat, with wired glass

and muntens BA-16

Historical Significance Very Significant

> Condition Poor

Repair/Replace No

Quantity 2

in East and West halls



Element Code CL-03

Element Code Skylight, round vault w/ wired

glass

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Barrel arch



Element Code CPP-1

Element Code Gray Georgia marble column,

polished, monolithic, on tripartite

pedestal

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Main Columns within

atrium/Rotunda space.



Element Code CPP-2

Element Code Gray Georgia marble post,

hollow

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes reveal between stones, 1 1/2"

wide, recessed 3/4". First

coridoor



Element Code CL-04

Element Code Plaster ceiling, smooth, flat,

painted

Historical Significance Significant

Condition Good

Repair/Replace

Quantity

Notes top of the drum area, painted

with sky and seagulls. Seagulls

added at a later date.



Element Code Gray Georgia marble post, solid

Historical Significance Significant

Condition Good

Repair/Replace

Quantity

Notes Solid - in the 1st floor corridoor.

Element Code CPP-3

Element Code Marble column, short

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Columns lining the North and

South sides of the Rotunda.







Element Code CPP-3

Element Code Marble column, short

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Columns lining the North and

South sides of the Rotunda.



Element Code CR-16

Element Code Stone Entablature

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

with various marble banding, Notes

large dentils, egg & dart, wolf head motif. Found in the Drum

area of dome - Lower



Element Code CPP-4

Element Code Oolite column, painted

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes 3rd and 4th floors only. On the

4th floor, they are in groupings of three. Original to the building though the wall is new. Painted capitols, painted recess in center

pilaster.

Element Code CR-16

Element Code Stone Entablature

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes with various marble banding,

dentils, egg & dart, wolf head motif. Wreaths along flat surface - seem to be holly/oak

leaves with berries.





Element Code CR-18

Element Code Painted Entablature

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes 4th floor. Contains plaster

> detailing as seen in the stone entablature - painted with gold leafing. Found in the Corridoor

Element Code CR-7

Element Code Ornamental band: stenciled

panel beneath cornice

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes found on the 1st floor corridoors.

Gold leaf.

Element Code F-2

Element Code Tile floor, hex & square, mosaic

Historical Significance Significant

> Condition Poor

Repair/Replace No

Quantity

Notes border has Greek key pattern.

Seen only on the 3rd and 4th

floor corridoors.







Element Code CR-2

Element Code Plaster cornice: crown molding,

classical and simple

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

Notes 3'-10" height, polychromed.

Found in the 3rd floor corridoor



Element Code Gray Georgia marble floor,

polished square

Historical Significance Very Significant

> Condition Fair

Repair/Replace No

Quantity

Notes variegated inlaid marble

patterns. Vermont marble, a darker grey, inlayed between the Rotunda columns. The marble flooring is horizontal tiles

layed brick style.

Element Code F-7

> Element Code Terrazzo floor, light green, with

white and black specks

Historical Significance Non-Contributory

> Condition Good

Repair/Replace No

Quantity

Replaced the glass blocks used Notes

originally.









Element Code HC-10

Element Code vent

Historical Significance Non-Contributory

Condition Good

Repair/Replace No

Quantity

Notes at entry to room 332



Element Code HC-17

Element Code vent with grille, ornamental

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity

Notes



Element Code L-02

Element Code Ceiling lamp mounted, Metal

rim, 1/2 round globe

Historical Significance Very Significant

Good Condition

Repair/Replace No

Quantity

Notes



Element Code L-04

Element Code Brass chandelier: 18 (16+1+1)

globes, eagle, chain

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes



Element Code L-05

Element Code Historic brass fasces lamp post,

with octagonal marble base,

with ram's head and frosted

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Notes at entry to House



Element Code L-07

Element Code Wall lamp, half-round globe in

plaster "ram" cartouche

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Above entablature - 4th floor Notes

corridoors



Page XIX.IX.126

Element Code L-11

Element Code Ceiling lamp suspended,

incandescent, 1/2 round globe,

historic

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity 44

Notes



Element Code L-19

Element Code Brass ceiling lamp, 6 sided, with

eschutchion, medallions

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes at entry to Senate, Supreme

Court & House



Element Code M-22

Element Code Classical plaster moulding, at

doorways

Historical Significance Very Significant

Condition Good

Repair/Replace No

Quantity

Seen at the portals to halls Notes

> behind lunettes, east and west ends of the Rotunda and at, and above the doors to the Rotunda piers on the 4th floor and above the large arch ways forming the

Rotunda dome.

Element Code MS-3

Element Code Fire hose cabinet, glass, metal,

recessed in wall

Historical Significance Non-Contributory

> Condition Good

Repair/Replace No

Quantity 2

Notes



Historical Significance

Contributory

Condition Poor

Repair/Replace

Quantity

There are about 8 benches in Notes

> the Rotunda area. They have been given a faux finish to resemble the marble. Replacement should be

considered

MS-5

Element Code Corbel, winged animal,

ornamental plaster

Condition Good

Repair/Replace

Quantity

Notes Some sort of Griffen creature -

sits in the 4 corners of the

Rotunda



Element Code

MS-17

Element Code Wood Bench

Element Code

Historical Significance Very Significant



Element Code P-15

Element Code Porcelain drinking fountain, free-

standing (Crane Corwith)

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes One sits on the East side under

the Grand stair landing area.

Element Code ST-10

Element Code Grand Stair. Marble

risers; newel post, round, polished, with base, shaft,

Historical Significance Very Signficant

Condition Good

Repair/Replace

Quantity

Good condition overall - could Notes

use some repair work in various places, marble is wearing. Very Usefull and attractive to the public. The underside of the landing - is being used for sculptural and aesthetic display.





Element Code P-2

Element Code Non-original drinking fountain,

wall-mounted

Historical Significance Non-Contributory

> Condition Good

Repair/Replace

Quantity 2

Notes



Element Code ST-22

Element Code simple stair, metal balustrade

with various ornamental

medallions.

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

4 sets. 2 East end. 1 North and 1 Notes

West. Not visible from Rotunda -

not decrative.



Element Code ST-9

Element Code Marble balustrade, with newels,

caps and railing

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes 3rd and 4th floors only. The

Knewell posts on the 3rd are plain faced, the 4th floor posts

have recessed panels.

Element Code W-2

Element Code Oolite slab wall, painted

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

Oolite on 3.4th floor coridor with

pilasters

Element Code W-7

Element Code Plaster wall, painted and smooth

Historical Significance Very Significant

> Condition Good

Repair/Replace No

Quantity

and West ends above the lunette

mural panels.

Above the Rotunda archways on the 4th floor and also at the East











Element Code Gray marble wall, polished

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes Coering the 1st floor corridor

and rotudna piers. The Piers house recessed niches and pilasters (same material) for

statuary.

Element Code W-3

> Element Code Murals, oil on canvas

Historical Significance Very Significant

> Condition Good

Repair/Replace No

> Quantity 12

> > Notes In the Rotunda, 4 lower

(pendentive) and 8 upper (frieze). 2 either end of the Rotunda in the Lunettes

Element Code WN-5

Element Code Double hung window

Historical Significance Significant

> Condition Good

Repair/Replace

Quantity

Notes found in the Rotunda Drum.

They were rebuilt in 1995. Further notes on these can be found in the exterior survey









Element Code WS-2

Element Code Marble wainscot, polished



Historical Significance Very Significant

Condition

Repair/Replace

Quantity

Notes Along the Rotunda walls on the 2nd floor the wainscot is

marble. The construction includes a base and chair rail. Large size to to fit scale of

Atrium area.

300

House of Representatives Chamber

Dimension/S F

Original Use

House of Representatives Chamber Preservation Level I



Notes see Section X. Finishes for historic palette. This chamber has varied more than other in its color scheme.

Element Code BA-14

Element Code Ornamental Band on cove

ceiling as described

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes shields (lion heads, 5pt stars,

swag,scroll, foliation) shallow band of rosettes-- applique beam on curve continuing across actual beams

Element Code BA-16

Element Code Muntens supporting skylight

panes

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code BA-15

Element Code Deep coffered ornamental (as

BA-14) beam supporting

skylights

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes inbetween skylight with rosettes

with ornamental bands (egg/dart top, bead bottom). Molding leads to skylight sash. The perimter band has plaster fruit

theme.

Element Code CL-02

Element Code Skylight, flat, with wired glass

and muntens BA-16

Historical Significance Very Significant

Condition Fair

Repair/Replace Replace

Quantity 48 panes

Notes side panels, 24 panes

(2@4x6;6@3x8); corner panels, 12 panes art glass, polychrome foliated

(original?) replaced glass doesn't match pattern, color





Element Code CL-15

Element Code 1/4 round cove vault ceiling with

ornamental Band and panels with molding as described

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes same molding as wall, but

flower motif at corner rather than

medallions

Element Code CPP-16

Element Code Composite capitals with

acanthus leaves, scroll, cherubs, painted plaster

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 16

Notes





Element Code CPP-15

Element Code Tapered Golden onyx pilasters

with composite capitals with (CPP-16) Composite capitals

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 16

Notes



Element Code CR-16

Element Code Stone Entablature



Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Entablature, incl. Crown

molding, egg/dart, dentils, crown molding, Rectangular plaster panels over column capitals, gilt/painted, Fasces panels, gilt/painted plaster. Work is of plaster, with paint and gold

leafing.



Element Code CR-17

Element Code Intermediate Entablature

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Found just under the Banister

railing. Contains various banding in marble, dentil, egg & dart

motifs.

Element Code D-07

Element Code Wood Panel door with

decorative metal wood-grained

casing

Historical Significance Significant

> Good Condition

Repair/Replace No


> Quantity 1pr

> > Notes









Element Code Carpeted floor, on pad

Historical Significance Contributory

> Condition Good

Repair/Replace

Quantity

custom pattern; floor slopes up

[raised] for wiring to each desk. Original floor unknown. Carpet is laid above platform allowing

space for electric circutry





Element Code Metal wood-grained panel door

with matching casing

Historical Significance Significant

> Condition Good

Repair/Replace No

Quantity 2

Notes



Element Code E-17

Element Code Electronic message board

Historical Significance

Condition

Repair/Replace

Quantity

Notes

Element Code F-24

Element Code Raised gallery floor

Historical Significance Non-Contributory

Condition Fair

Repair/Replace Yes

Quantity

Notes



Page XIX.IX.134

300

Element Code HC-17

Element Code vent with grille, ornamental

Historical Significance Signifiacnt

Condition Good

Repair/Replace

Quantity

Notes



Element Code L-12

Element Code Indirect cove lighting

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity

Notes



Element Code M-1

Element Code Golden Onyx casing w/ arched

lintel cornice, plaster foliated ornament, sega lily

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes Located over the North, South

and East doorways.





Element Code L-08

Element Code Fluorescent lights

Historical Significance Non-Contributory

Condition Fair

Repair/Replace

Quantity

Notes above skylight, fixtures are so

> large/numerous as to block natural light, making their use requisite during the day as well

as night.

Element Code L-26

Element Code Brass wall sconce, projecting

arm, fasces shaft, metal rim w/ swags, rams head, and smoked

Historical Significance Significant

> Condition Good

Repair/Replace No

> Quantity 10

> > Notes



Element Code M-3

Element Code Golden Onyx casing and lintels,

simple

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

over west doors Notes



Element Code NHF-1

Element Code Cushioned theater seating

Historical Significance Non-Contributory

Condition Good

Repair/Replace

Quantity

Notes gallery seating



Element Code W-27

Element Code Flat plaster wall, painted, with

panels W-28


Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code W-28

Element Code Ornamental plaster wall panel

with molding as described

Historical Significance Very Significant

Condition Poor

Repair/Replace Repair

Quantity

Notes with 2 ornamental frames.

medallion blocks at corners; all

slightly gilded

Element Code W-3

0000 11 0

Element Code Murals, oil on canvas

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes in cove, east and west



Element Code W-3

Element Code Murals, oil on canvas

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes in cove, east and west

Element Code W-30

Element Code Frontispiece with single plaster

panel, ornamental frame, arched pediment, crown molding,

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes All painted plaster/marble with

exception of the marble pilasters.





Element Code WS-1

Element Code Golden Onyx wainscot, polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes gold onyx. This wainscot includes the base and chair rail.

includes the base and chair rail. It appears to be constructed together and so considered one

piece.




331

Supreme Court Chamber

Dimension/S F

Original Use

Supreme Court Chamber Preservation Level I



Notes

Element Code BA-04

Element Code Ornamental plaster beam,

painted, running ornament

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes 4 intersecting beams, 2 in either

direction overlaping around the skylight. They, along with the perimeter of the room could contain an "entablature". The detailing here contains banding, stenciled greek key in gold leaf and paint. Plaster egg & dart, bead & real, wolf head and dentils. The Plaster work is considered the cornice/ if called out seperately from the entablature. The underside of the beams contains a guioche pattern painted and accented in

gold leaf.

Element Code CL-02

Element Code Skylight, flat, with wired glass

and muntens BA-16

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes



Element Code BA-15

Element Code Deep coffered ornamental (as

BA-14) beam supporting

skylights

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes The intersecting beams create

an outline for the skylight. The "entablature" consits of similar detailing to the beam work painted banding, stenciled greek key in gold leaf and paint. Plaster egg & dart, bead & real, wolf head and dentils. The differing item is the foliated band in gold leaf. The leaf is possibly oak. The skylight sits above.



Element Code CPP-15

Element Code Tapered Golden onyx pilasters

with composite capitals with (CPP-16) Composite capitals

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes







Element Code CR-7

Element Code Ornamental band: stenciled

panel beneath cornice

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code D-05

Element Code Metal wood-grained panel door

with matching casing

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity 1pr + 2

Notes



Element Code E-10

Element Code Vacuum outlet

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes possibly only 1, found at the

South East corner

Element Code F-12

Element Code Carpeted floor, glue-down

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code HC-10

Element Code vent

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes In the base/wainscot and also in

the central panels North and

South walls.



Element Code M-23

Element Code Golden Onyx threshold, polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes at the main entrace door entry

only.



Element Code M-3

Element Code Golden Onyx casing and lintels,

simple

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes surrounding all door ways



Element Code MS-9

Element Code Chair lift, ADA

Historical Significance Contributory

Condition Good

Repair/Replace

Quantity

Notes Unsure on historicity



Element Code SP-24

Element Code Court balastrade on floor with

gate

Historical Significance Very Significant

Condition Poor

Repair/Replace

Quantity

Notes





Element Code MS-1

Element Code Accessories, as noted

Contributory

Condition Good

Repair/Replace

Historical Significance

Quantity

Notes Clock attached between

wainscot and plaster wall panel, behind the dias. Unsure on historicity. Square/ seem to be

more modern.

Element Code SP-1

Element Code Wall-hung art piece

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity 1

Notes Culmer painting





Page XIX.IX.141

Element Code W-28

Good

Element Code Ornamental plaster wall panel with molding as described

Historical Significance

Very Significant

Condition

Repair/Replace

Quantity

Notes

panels defined with paint and gold leafing. Panel seems to be inset 3/4 times with banding, bead & real, Egg & dart & wolf head. The exterior panel has a square medalion in each corner, with a flower motif of some kind. The interior panel is accented with Dog ears. There are 4 large panels central to each wall. The North and South have a top cartouche with the Justic Scale. The East and West cartouches have books. Each large panel is flanked by 2 panels which appear to be approximately half sized in width.

Element Code W-29

Element Code Golden onyx frontispiece with Ionic pilasters (with capitals of

gilt/painted plaster)

Historical Significance

Very Significant

Condition Good

Repair/Replace

Quantity

Notes Archway, fill consists of gold leaf follage - surrounding a clock. The clock in not historic, but there is plaster base large enough to hold the clock. Unsure on what was there originally. On either side beneath the pediment is a marble carved corbal bracket



Element Code W-29

Good

Element Code Golden onyx frontispiece with

Ionic pilasters (with capitals of

gilt/painted plaster)

Historical Significance

Very Significant

Condition

Repair/Replace

Quantity

Notes



Element Code W-7

Element Code Plaster wall, painted and smooth

Historical Significance

Very Significant

Condition Good

Repair/Replace

Quantity

Notes





331

Element Code WS-1

Element Code Golden Onyx wainscot, polished

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes




370

Senate Chamber

Dimension/S F

Original Use Senate Chamber

Preservation Level I



Notes has 2 coat/listening rooms on the west side now used for storage

Element Code BA-14

Element Code Ornamental Band on cove

ceiling as described

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Rosette medallions on dark field

color.

Element Code BA-16

panes

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes

Element Code CL-02

Element Code Skylight, flat, with wired glass

and muntens BA-16

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Considering the construction, the

base and chair rail are considered elements in the wainscot and are not called out

UTAH STATE CAPITOL RENOVATION PLANNING SITE ANALYSIS COOPER ROBERTS ARCHITECTS TEAM

seperately.



Element Code BA-15

Element Code Deep coffered ornamental (as

BA-14) beam supporting

skylights

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes



Element Code CL-02

Element Code Skylight, flat, with wired glass

and muntens BA-16

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes

Element Code CL-07

Element Code Acoustical tile ceiling, glue-on


Historical Significance Non Contributory

Condition Fair

Repair/Replace

Quantity

ites Used only above the gallery area





Element Code CL-15

Element Code 1/4 round cove vault ceiling with

ornamental Band and panels with molding as described

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes The recessed panels with egg &

dart plaster work finished with gold leafing. The surrounding skylight band motifs - guicho, rope, open bosses with a cartouche on it's side.



Element Code creamy white onyx travertine

posts

Historical Significance Significant

Condition Good

Repair/Replace No

Quantity 10

Notes in gallery





Element Code creamy white onyx travertine

pilaster

Historical Significance

Very Significant

Condition Good

Repair/Replace

Quantity 6

Notes on north wall



Element Code CPP-20

Element Code Ceamy white onyx travertine

Columns with capitols

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes





Page XIX.IX.146

Element Code CR-16

Element Code Stone Entablature

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes Includes running bands of onyx

and plaster, detailing in gold leaf. Details include dentils, egg & dart, cornocopia motif with spilling fruit. The backgroung contains leaf & berry and flower and leaf motifs. The modillions show acanthus leaves on the

underside.

Element Code E-17

Element Code Electronic message board

Historical Significance Non Contributory

Condition

Repair/Replace



Element Code D-05

Element Code Metal wood-grained panel door

with matching casing

Historical Significance Significant

> Condition Good

Repair/Replace No

> Quantity 1pr + 6

Notes with M-6, B-7 to Senate

Chamber



Good

Quantity

Notes



Element Code F-12

Element Code Carpeted floor, glue-down

Historical Significance Contributory

> Condition Good

Repair/Replace No

Quantity

Notes Carpet laid over platform to

allow room for electric circutry



Element Code HC-19

Element Code Metal "grid" air grille, painted

gold on wall

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes several vents, found in the

wainscot, frieze and north wall.

Element Code NHF-1

Element Code Cushioned theater seating

Historical Significance Contributory

Fair Condition

Repair/Replace

Quantity

Floor mounted into the gallery Notes

Space

Element Code W-2

Element Code Oolite slab wall, painted

Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Painted oolite, with thick jointing. Notes

Brick like appearance.



Element Code M-4

Element Code Creamy white onyx casing

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Notes Surrounding all doors



Element Code ST-23

Element Code Brass gallery handrail,

ornamental

Historical Significance Very Significant

> Condition Good

Repair/Replace

Quantity

Was replaced in the 1950s after Notes

failing. Top railing is not historic.

Element Code W-29

> Element Code Golden onyx frontispiece with

Ionic pilasters (with capitals of

gilt/painted plaster)

Historical Significance Very Significant

> Good Condition

Repair/Replace

Quantity

Notes









Element Code W-3

Element Code Murals, oil on canvas



Historical Significance Very Significant

Condition Good

Repair/Replace

Quantity

Notes North wall. Divided into 5

sections by onyx pilasters

380

Main Corridor 3rd floor

Dimension/S F

Original Use Main Corridor 3rd

floor

Preservation Level I

Notes